

- Firmware Changelog -



IEB-54F0036M0A
IED-54F0036MBA
IED-64M2812MBA
IEB-64M2812M0A

v1.3.12

- DHCP are default setup after reset

v1.2.6 series start version