

- Firmware Changelog -



IEB-54F0036M0A
IED-54F0036MBA
IED-64M2812MBA
IEB-64M2812M0A

V3.0.8

Important info, update @ version v3.0.8 should be done in 3 steps if current version are v1.3.12 proceed as follow ->1.3.99 ->2.0.99 ->3.0.8

- (New) Smart Focus automatically stopped under extremely low light condition
- (Bug fix) Link speed 10Mbps was not supported
- (Bug fix) Audio setup was not set at default by RESET
- (revision) Onvif Media2 - Bitrate control function added

v1.3.12

- DHCP are default setup after reset

v1.2.6 series start version