



13/05/2021

Dear Partner,

Please find below FW v4.2.1.0 (30193) release info for 2MP S-Sight v2 IP Cameras.

1. Fixed night performance issue where in some cases, the image will become extremely dark after the camera was exposed to bright lights.
2. Minor bug fixes and stability improvements.

You can update to v4.2.1.0 (30193) from any version running on the IPC.

All settings will be saved after the update.

The Firmware is available to download from Provision-ISR website (www.provision-isr.com) for all 2MP S-Sight v2 (Model names xxx-**320IPS**-yy)

Best Regards,
Provision-ISR Technical team