

## **TECHNICAL ANNOUNCEMENT** February 2024

**SUBJECT:** Firmware release for 4MP LPR IPC Models: 16-340LPRN-MVF1 / 16-340LPRN-MVF2

FW: v5.1.1.0 (54655) RD20240122

## **LIST OF IMPROVEMENTS:**

1. Solving the below bug which we announced on December 2023.

"In some certain circumstances the camera is not sending some license plates snapshots to the NVR."

Please feel free to contact us if you have any question.

**Provision-ISR Technical Team**